


# CUM 740

## Transmitter for Turbidity and Solids Contents

### Operating Instructions



## Table of contents

1.	Safety instructions .....	page.....	2
2.	General information .....		3
	2.1 Assembly instructions.....		3
	2.2 Functions.....		4
	2.3 Maintenance instructions.....		5
3.	General description.....		6
4.	Front view of control panel.....		6
5.	Programming guidelines.....		7
	5.1 Measurement Cycle .....		8
	5.2 Parameter Entry .....		8
	5.3 Calibration Procedure.....		9
	5.4 Solids Input.....		10
	5.5 Change Frequency.....		10
	5.6 Select Configuration .....		11
	5.7 Selection of Foreign Language .....		12
	5.8 Reading Error Messages.....		13
	Error Messages .....		13
6.	Putting into operation.....		14
	6.1 Calibration .....		14
	6.1.1 2-point-calibration:(usually sufficient) .....		14
	6.1.2 Multipoint calibration.....		15
7.	Inputs and Outputs .....		19
	7.1 Control Inputs .....		19
	7.2 Signal Outputs.....		19
	7.3 Analog Output .....		19
8.	Adjustment ranges of concentration.....		19
9.	Terminal assignments .....		20
10.	Connecting assignments of probe plug, -socket and extension cable .....		20
11.	Serial interface CUM 740 (Option) .....		21
12.	Special version "2 sensors" .....		22
13.	Technical data .....		24
	Annex .....		26

## 1. Safety Information / Sicherheitshinweise / Informations de sécurité



- Only authorized personnel is allowed to carry out installation, putting into operation, handling, maintenance and repairs applying the relevant safety rules for mechanical engineering and electrical engineering especially norm EN 292.

**NOTE: Improper handling may cause personal injury or material damage!**

- The declaration of conformity is only with reference to the measuring transformer and not its assembly.



- Installation, Inbetriebnahme, Handhabung, Wartung und Reparatur darf nur von autorisiertem Fachpersonal ausgeführt werden. Anzuwenden sind hierbei die einschlägigen Sicherheitsrichtlinien für Maschinenbau und Elektrotechnik, insbesondere die Norm EN 292.

**ACHTUNG: Durch unsachgemäße Handhabung können Personen- und Sachschäden entstehen!**

- Die Konformitätserklärung bezieht sich nur auf den Meßumformer und nicht auf dessen Montage.



- Installation, mise en service, manipulations, entretien et réparation doivent être effectués que par des techniciens qualifiés. Les instructions de sécurité machines et électrotechniques doivent être appliquées, et tout particulièrement la norme EN 292.

**ATTENTION: Des manipulations inappropriées peuvent entraîner des dommages matériels et corporels!**

- Le déclaration de conformité se réfère seulement au système de mesure et non à son montage.

## 2. General information

### 2.1 Assembly instructions

- The measuring location must allow a representative measurement.
- We recommend to equip the system with an additional protective roof against direct weather factors (e.g. deposition of snow).
- Holding devices must ensure that the weight of the device (approx. 5 kg) can be picked up without vibrations.
- Install the system at a location which can be easily accessed in order to avoid danger to operating personnel (e.g. at putting into operation, maintenance and cleaning).
- The probe must be made easily accessible as well.
- The construction of the device must be secured with 1A.
- Any cable connections have to be laid in a manner that prevents mechanical damages and disturbances by other cables.
- The load capacity of the probe cable is maximally designed for the probe with probe weight and screen grid.
- The probes are measuring technical devices. Please note that the measuring windows cannot be damaged, e.g. at the built-in version by weld beads in the pipeline.

---

## 2.2 Functions

**NOTE:** For a correct functioning of the device please proceed according to the operation instructions

- In the annex of this manual there is a blank which can be used to fill in by hand all parameters specific to measuring location (important e.g. in case of loss of data).
- All adjusted parameters are battery-buffered. The battery-life is approx. 5 years.
- In the terminal cabinet, there are all fuses of the measuring transformer (refer to item 9., “terminal assignments“)
- Note that generally for all probe types strong scrapers and heavy contamination of the measuring windows may impair the measuring ability.

- 

**ATTENTION!**

Start the device only when the probe plug is connected and screwed!  
Plugging in or out of the probe only when the device is off!

## 2.3 Maintenance instructions

### Every four weeks:

#### Cleaning of the probe:

Remove rough deposits at the cable with a cloth.

Clean the soiled probe with a brush and soap-suds.

ATTENTION: Fact is that the measured value may be impaired by heavy scratches or damages at the measuring windows.

**The cleaning cycle may be extended depending on application (experience)**

### Yearly jobs:

#### General function test:

Electronics:

Check probe calibration.

(Battery buffer: Durability of the battery = 5 years)

Tighten cable terminals and control their position.

### 3. General description

The CUM 740 is controlled by a 16-bit-microcontroller and allows the following functions:


- Detection and processing of measured values
- Special menu-driven routine with an alphanumeric display
- Monitoring of the system and probes
- Storage and control of user parameters

All user parameters such as measuring range, alarms, cleaning intervals and adjustment of output signals are fed in a menu-driven routine and stored in a battery-buffered memory.

The 6 position keypad is used to enter program parameters and to move horizontally and vertically in the menus on the display. During the measurement cycle, the numeric results are shown on an LCD-display and at the same time on an LED-display which can be read from a longer distance.

LEDs are integrated in the keypad to show different states of the system, control and outputs

### 4. Front view of control panel



1 = LED-Display

2 = LCD-Display

3 = Keys for operation:

- M - for the main routine "MEASUREMENT"
- CE - for backwards movements in the submenu
- ↑ - for backwards movement in the main menu
- ↓ - to increase numeric values in the submenu
- ⇓ - for forward movement in the main menu
- ⇓ - for decrease of numeric values in the submenu
- E - to confirm main menu items
- to confirm numeric values and parameters
- to change the display during the measurement
- R - for adjusting the calibration factor


4 = Control LEDs:

- LED 1 (M) Alarm A
- LED 2 (CE) Alarm B
- LED 3 (↑) Range exceeded
- LED 4 (⇓) Below range
- LED 5 (E) Call in error display
- LED 6 (R) Operation cleaning program

5 = Power switch

## 5. Programming

The main menu includes the following titles always shown in capital letters:



After the instrument is powered on, it switches automatically into the measuring state. By pressing the “M” key you get the main routine MEASUREMENT (same from almost any main routine or sub routine). If the measurement program is not automatically started after switch on (e.g. if the system has not been configured yet), press the “M” key before turn on and until the word MEASUREMENT is shown on the LCD display.

### General:

- a) Vertical movement in the main menu is done by the arrow keys ‘↑’ and ‘↓’.  
To enter a main item press the “E” key.

‘↓’ forward movement in the main menu  
 ‘↑’ backward movement in the main menu  
 ‘E’ enter main routine, continue in each submenu  
 ‘M’ move to the start of the main menu (routine MEASUREMENT).

- b) Horizontal backward and forward movement at each selected submenu by using the “E” and “CE” keys.

‘E’ forward movement at the submenu  
 ‘CE’ backward movement at the submenu

- c) Within a subroutine, numerical values can be increased and decreased by continuously pressing keys ‘↑’ and ‘↓’. The selection is accepted by pressing the “E” key.


‘↑’ numerical value increase  
 ‘↓’ numerical value decrease  
 ‘E’ accept value and store it

- d) **Code no.** to get into the submenus: Enter the number “91”.

### 5.1 Routine MEASUREMENT / Main Menu

```

----- MEASUREMENT
      |
      | Measured value      (mg/l, g/l, FTU, NTU, %, ppm)
      |
      | Analog output      (mA)
      |
      | Frequency          (Hz)
  
```



**Function:**

Detection, evaluation and display of the probe signal, of the analog current and the probe frequency as well as setting the alarm switches

**Operation:**

By once pressing the key “E” the display for the physical measured value is switched to the corresponding analog output signal (current) By pressing the key “E” twice the measured probe frequency or 505 Hz appear as error display on the LCD display, as well as the corresponding measured value on the LED display.  
Return into the main menu with the key “M”.


Pressing the “K” key allows the adjustment of the calibration factor (see 5.6, “configuration”).

- ‘E’ selection of display measured value or display analog output and frequency
- ‘K’ adjust calibration factor
- ‘M’ return to main menu

### 5.2 Routine PARAMETER ENTRY

```

----- PARAMETER ENTRY
      |
      | Measurement range - start (g/l, FTU, NTU, %, ppm)
      |
      | Measurement range - end   (g/l, FTU, NTU, %, ppm)
      |
      | Alarm A                   (g/l, FTU, NTU, %, ppm)
      |
      | Alarm B                   (g/l, FTU, NTU, %, ppm)
      |
      | Damping                   (s)
      |
      | Cleaning interval         (min)
      |
      | Cleaning period          (s)
  
```



**Function:**

- Measuring range - start and end:  
 Selectable concentration range within a calibration curve, the analog output (signal current 0-20 mA or 4-20 mA) being assigned in linear manner.  
 The display (LED and LCD) only indicate values which are higher than half of the measuring ranges at the start and smaller than double the ranges at the end.  
 Range start and end values are the same for setting the alarms.

- Alarm values Alarm A and Alarm B:  
Concentration-threshold values for alarm relays. The switch hysteresis is  $\pm 2\%$  each.
- Response Time (Damping) (1 - 600 s):  
The response time sets the time interval period in seconds, by which the probe average signal (corresponding to the concentration value) can be arithmetically determined. The probe signal is measured every 0.5 s. The selected value is valid for the actual measurement as well as the calibration of the probe (see section 5.3).
- Cleaning interval (1 – 720 min):  
Selection of a time interval (in minutes) for a special cleaning routine (if selected).
- Cleaning period (1 – 600 s):  
Time period of the probe cleaning process in seconds.  
("Connection of solenoid valve" see annex)


**Operation:**

Movement through the submenu and selection of numerical values refer to item 5.b) and 5.c) "General".

**5.3 Routine CALIBRATION**

```

----- CALIBRATION
      |
      | Input of code number      (91)
      |
      | Number of measuring points (n)
      |
      | Measuring points 1...n    (Hz)
  
```



**Function:**

For calibration the probe signals (measuring points 1...n) which are measured by media of comparison with known concentration are detected and stored in any order.

Before delivery the CUM740 is calibrated at the factory (refer to item 5.6 CONFIGURATION, factory adjustment). A calibration specific to application is necessary, as far as "standards" (e.g. formazine) for turbidity is not worked with.

**For calibration we generally recommend to set the damping to 2 seconds.**

**Operation:**

- Code number:  
Two-digit number. If it is incorrect, the submenu will be left and the main menu routine MEASUREMENT will be returned to.
- Number of measuring points:  
Number of media points for comparison to be used for calibration (min. 2, max. 8).
- Measuring points:  
Display of every measuring point number and the detected probe signal (response time / damping please refer section 5.2, "parameter entry"). Storing of measured value by pressing the key "E". (Attention: the previous measured value of this measuring point number is overwritten.)  
Return one measuring point by "CE". Press the key "M" to return into the main menu.

**Attention: Please use for zero-calibration (clear water) a black vessel (bucket 10 ltr.). Please cover bucket during calibration to avoid artificial light.**

### 5.4 Routine SOLIDS INPUT

```

----- SOLIDS INPUT
      |
      Input of code number      (91)
      |
      Measuring point 1...n    (mg/l, g/l, FTU, NTU, %, ppm)
  
```


**Function:**

In this submenu concentration values of the media (known or subsequently detected in the lab) corresponding to the detected probe signals from routine 5.3 “calibration“ (for the measuring points 1...n) are entered and stored.

**Operation:**

For movement in the submenu and selection of numerical values, please refer to section 5.b) and c).

At the end return to the main menu with key “M“. Setting the 3. digit: Additional to key ‘↑’ or ‘↓’ press key ‘E’.



### 5.5 Routine FREQUENCY

```

----- FREQUENCY
      |
      Input of code number      (91)
      |
      Frequency 1...n          (in Hz)
  
```


**Function:**

At frequency input, the probe signals (see 5.3 “calibration“) detected for the measuring points 1...n, can be examined and manually changed if necessary.



**Operation:**

Movement in the submenu and selection of numeric values refer to section 5.b) and c) “General“.

At the end return to the main menu with key “M“.



## 5.6 Routine CONFIGURATION



**Function:**


- Code number: Two-digit number. If it is incorrect, the submenu will be left and the main menu routine MEASUREMENT will be displayed.
- Probe type:
  - Select type of used measurement probe. At present the following standard probes are available:
    - CUS 65-A/, -B/, -C/, -D/, -E
    - CUS 61 / 62 / 63 / 64
    - free parameters (without probe-type-monitoring and detection of pollution)
  - further probes according to table on page 19 chapter 8

- Factory adjustment:

By pressing both arrow keys at the same time standard parameters are read in (corresponding to the selected probe type). Please find a table about these standard parameters in the annex of this manual.

**Attention:** By entering the factory adjustment the previous stored values are overwritten. If a calibration specific to media is requested, press the key "E" and proceed as described under item 6, "putting into operation".

- Unit of measure: Select the physical units to measure the concentration. Allowable units are dependent on each type of probe selected.
- Calibration factor: Linear adaptation factor of the calibration curve at low movements of the medium being measured. Input limits: ± 25% (is set on 0% when factory adjustment is selected).



- Analog output: Select if the defined concentration measuring range (refer to 5.2 "parameter entry") is to be displayed in a linear manner on a current range of 0-20 mA or 4-20 mA. (Corresponding to the range start is either 0 mA or 4 mA but the end is always 20 mA.)
- Alarm A and B, contact error: Select the function of the corresponding relays for NO or NC contact.

**Operation:**

For movement in the submenu and selection of numerical values, please refer to section 5.b) and c) "General". At the end return to the main menu with key "M".


**5.7 Routine LANGUAGE**

```

----- LANGUAGE
      |
      German - English - French - Swedish
      - Norwegian - Dutch - Danish - Spanish
      (if requested Japanese, Italian, Polish, Finnish)
  
```

**Operation:**

Select the change to a language with keys '↑' and '↓' and press the "E" key to store. Return to main menu with key "M".




## 5.8 Routine ERROR DISPLAY

----- ERROR DISPLAY  
 |  
 Error report

**Function:**

**Error messages MTF software Rev. 4.6:**

- 0 = too high concentration
- 2 = wrong type of probe
- 3 = no probe signal
- 4 = no probe signal / probe contaminated
- 5 = test calibration



**Error text brief description:**

- 0 = too high concentration is displayed if the specified measuring range end (refer to PARAMETER ENTRY 5.2) is exceeded by more than two times.
- 2 = wrong type of probe is displayed if the probe connected does not correspond with the selected type (refer to CONFIGURATION 5.2). ("Free parameters" without probe type monitoring and dirt detection).
- 3 = no probe signal is displayed if the measuring transformer does not receive a frequency signal from the probe (e.g. cable breakthrough). Error 3 results in a frequency display of 0 Hz independent from output "disturbance".
- 4 = no probe signal / probe contaminated is displayed, if the measuring transformer receives no frequency signal from the probe and additionally receives a status message (e.g. contaminated probe window / does not apply to the thick sludge probe type CUS 64 / CUS 65-E). Error 4 results in a frequency display of 505 Hz independent from the output "disturbance".
- 5 = test calibration is displayed if the calibration frequencies lie closer to each other than 15 Hz (e.g. if the saved calibration frequencies were overwritten by mistake).

- Error message at "free parameters":**
- C - measuring range exceeded
  - no probe signal
  - test calibration

The signal output "error" is only set after a cause of error has been existing for at least 10 s.

**Operation:**

The error messages can one after another be called up with "E" and called back with "CE". After the last message you will be asked to return into the main menu by pressing the key "M".

**Causes for disturbances** in the system can be found at the measuring probe, the measuring transformer, the cable distance between both units as well as in the range of mains supply. If in a first putting into operation all application questions are clarified and there are still some disturbances, or disturbances suddenly appear in a so far duly functioning measurement, you have the possibility to send the defective unit to our following address(see back page of these Operating Instructions).

## 6. Putting into operation

A pre-programmed and adjusted amplifier starts the measuring cycle automatically after being switched on, a manual setup is not necessary.

The probes **CUS 63 and CUS 65-D** are delivered with a pre-calibration of **0 - 100 FTU**. Please check if the data in routine "FREQUENCY" is identical to the data of the calibration sheet of probes. If the data is not identical, please enter the data of the calibration sheet for probes at the routine "FREQUENCY" .

The probes **CUS 61 / 62 / 64 und CUS 65-A/, -B/, -C/, -E** are pre-calibrated at the factory with  $\text{SiO}_2$  .

**A calibration specific to the application is normally necessary.**

**Note:** The probes **CUS 64 und CUS 65-E cannot be set up or calibrated in clear water area.** The probe is designed for applications in thick sludge. Representative values can only be expected, if the lowest calibration point lies at a sludge concentration > 1%. (0.8 % are possible depending on sludge nature.)

You obtain calibration values close to practice by assigning the raw signal of the probe (frequency) to the solids determination of the laboratory over a defined period of time (1 week). To perform this under process conditions, the probe has to be mounted at the pipe.

Often a calibration specific to the medium is carried out by the customer (e.g. with activated sludge of a wastewater treatment plant). Please refer to the following example:

### 6.1 Calibration

#### 6.1.1 2-point-calibration: (usually sufficient)

In most cases it is enough to work with a two point calibration, although the measurement converter CUM 740 allows to save up to 8 calibration points.

The two point calibration happens with tap water (1.measurement point) and with the sludge of the respective application (2.measurement point).

In order to carry out the two point calibration in the menu point „Calibration“ the amount of the measurement points have to be set on 2.

The probe which is to be calibrated will be dipped into a dark covered up bucket filled with tap water and the frequency is saved with the enter key. (This is not effective for the back-scattered probes CUS 64 and CUS 65-E).

As described the probe is to be installed with the respective application (e.g. aeration basin, sludge pipe) and the measured frequency saved again with the enter key .

It is to observe, that the measurement value is stabil.

Hereupon the sludge of the application of a representative specimen (1Ltr.) is pulled and the solid content is determined in the laboratory.

Through the menu point „place“, for the first measurement point, the concentration 0 e.g. g/l (PPM, mg/l, %) is put in and for the second measurement point the result of the laboratory predestination from the sludge specimen (e.g. g/l PPM, mg/l, %).

Should there be immediately little deviations to the compared measurements of the laboratory, they can be simply eliminated through the „calibration factor“ (key K).

This means a displacement of the calibration curve of + 25 % or - 25 %.

---

## 6.1.2 Multipoint calibration

### Example putting into operation TS-measurement with CUS 65-A:

**Setup procedure:** For a 4-point calibration you will need about 5 liters of activated sludge and 4 black buckets. The minimum bucket volume for calibration is 2 liters. The first bucket contains clear water for the zero point. The second contains a diluted sludge 1:1 (1 liter sludge and 1 liter water). The third contains the original sludge. For the fourth bucket which contains a thickened original sludge you should wait some time until you see the separation of water and sludge. Carefully pour out the water because the bucket should contain a thicker sludge than normal. To do this you will need about 3 liters of sludge.

After the probe calibration the concentration values will be analyzed in the lab.

**Important:** **During calibration the sludge must be stirred continuously with the probe in order to obtain a proportionate distribution of concentration.**

**Start programming:** Press and hold key "M" during powerup test and until the display shows "MEASUREMENT".

**Note:** If the probe signals change too slow on the display, please check at "PARAMETER" the response time and enter a smaller value. For calibration a damping of 2 seconds is generally recommended.

	MEASUREMENT	
1. Press $\uparrow$ 3x, display shows	CONFIGURATION	press key E.
	Code No.:	$\uparrow/\downarrow$ 91, press key E.
	Type of probe	$\uparrow/\downarrow$ CUS 65-A, press key E.
	Unit of measure	$\uparrow/\downarrow$ g/l, press key E.
	Alarm A	$\uparrow/\downarrow$ operating- or rest current, (make or break), then E.
	Alarm B	$\uparrow/\downarrow$ operating- or rest current, (make or break), then E.
	Error contact	$\uparrow/\downarrow$ operating- or rest current, (make or break), then E.
	-> M	press key M.
	MEASUREMENT	
2. Press $\uparrow$ 2x, display shows	CALIBRATION	press key E.
	Code No.:	$\uparrow/\downarrow$ 91, press key E.
	No. of points?	$\uparrow/\downarrow$ 4 (2 - 8), press key E.
Place probe in bucket 1 and stir, frequency with clear water ~ 4000 Hz.		
	1. Value	if zero stable, press key "E".
Place probe in bucket 2 and stir, frequency with diluted sludge ~3150 Hz.		
	2. Value	if value stable, press key "E".
Place probe in bucket 3 and stir, frequency with original sludge ~ 2210 Hz.		
	3. Value	if value stable, press key "E".
Place probe in bucket 4 and stir, frequency with thicker sludge ~ 1980 Hz.		
	4. Value	if value stable, press key "E".

	-> M	press key M.
	MEASUREMENT	
<b>3. Press ↓3x, display shows</b>	SOLIDS INPUT	press key E.
	Code No.:	↑/↓ 91, press key E.
	1. Value x.xx g/l	↑/↓ 0.00 zero-value, press E 0.00 g/l
	2. Value x.xx g/l	↑/↓ 1. lab-value, press E e.g. 3.5 g/l
	3. Value x.xx g/l	↑/↓ 2. lab-value, press E e.g. 6.3 g/l
	4. Value x.xx g/l	↑/↓ 3. lab-value, press E e.g. 8.5 g/l
	-> M	press key M.
	MEASUREMENT	
<b>4. Press ↓ 1x, display shows</b>	PARAMETER ENTRY	press key E.
	Range start x.xx g/l	↑/↓ Value, press key E.
	Range end x.xx g/l	↑/↓ Value, press key E.

Alarm A x.xx g/l	↑/↓ Value, then press E. switch value e.g. 5.6 g/l
Alarm B x.xx g/l	↑/↓ Value, then press E. switch value e.g. 8.5 g/l
Damping    x s	↑/↓ 1 - 600 s, press key E. e.g. 5
Cleaning interval xxx min	↑/↓ 1 - 720, press key E. Relay-interval time
Cleaning period xxx s	↑/↓ 1 - 600, press key E. Relay-active time
-> M	press key M.
MEASUREMENT	press key E.

MTF - Display normal

<b>5.88</b>
Meas. value <span style="float: right;">5.88 g/l</span>

During the measurement cycle the actual current output can be shown by pressing key 'E' once.

<b>16.6</b>
Analog output <span style="float: right;">16.6 mA</span>

During the measurement cycle the actual probe frequency and the value belonging to it can be displayed by pressing the key 'E' twice.

<b>5.88</b>
Frequency <span style="float: right;">2323 Hz</span>

## 7. Inputs and Outputs

### 7.1 Control inputs (+24V)

- 24 V DC „IN“ (terminals 24/25): Freezing of the measurement (The measurement is interrupted and the currently displayed value is “frozen“.)

For control of 24 V DC „IN“ you can use  $U_a$  (+24V, terminal 26).

**Attention:** Therefore terminal 27 (0V) has to be connected with terminal 24 (0V).

### 7.2 Signal outputs (switch contacts)

- “Alarm A“: Actuates exceeding or below limit value
- “Alarm B“: Actuates exceeding or below limit value
- “Hold“: Measurement interruption, values on hold
- “Error“: Error display at operation menu
- “Cleaning“: Switch contact for probe cleaning

The switch contacts are designed for DC 30 V / 1 A or AC 230 V / 2 A.

### 7.3 Analog output (I-1)

0/4 mA = Measurement range - start

20 mA = Measurement range - end (see 5.2, “Parameter entry“/function)

Configuration of analog output (see 5.6, “Configuration“ / analog output)

**Note:** Resistance max. 500  $\Omega$


## 8. Adjustment ranges of concentration

The measuring range (item PARAMETER ENTRY) can be defined within the following limits, dependent on which probe type and what kind of physical unit have been selected at item CONFIGURATION:


Type of probe	mg/l, ppm	g/l	FTU	%
1. CUS 61 / 65-A (SAM / SAD)	100 - 100 000	0.1 - 100		0.01 - 10
2. CUS 62 / 65-C (SAV)		0.3 - 400		0.03 - 40
3. CUS 63 / 65-D (SSN)	1 - 5000		0.5 - 1000	
4. CUS 64 / 65-E (SRH)		1.0 - 1000		0.1 - 100
5. CUS 65-B (SAH)		0.3 - 400		0.03 - 40
6. fr. Par.	0.1 - 10000	0.1 - 1000	0.02 - 5000	0.01 - 100

### 9. Terminal assignments:


Connection of 1 sensor:



Connection of 2 sensors:



### 10. Pin connection of probe plug, -socket and extension cable:



## 11. Serial Interface CUM 740 (Option):

Cable assignment:

RS 232-0 on CUM 740			COM 1 / 2 at the PC		
terminal	SUB-D 9 poles	Function	Function	SUB-D 9 poles	SUB-D 25 poles
23	3	TxD0	RxD	2	3
22	2	RxD0	TxD	3	2
21	8	CTS0	RTS	7	4
			CTS	8	5
20	5	GND	GND	5	7

Software protocol: **9600, N, 8, 1**

Output format: **ASCII**


The output of the results (measured value + measuring unit + CR) is effected continuously during the automatic measurement in second intervals. A configuration of the interface on CUM 740-side is not necessary.

## 12. Special version „2 sensors“

### 12.1 Menu (special version „2 sensors“)

Function and construction of the menu points are – disregarding unimportant exceptions – identical with the 1-sensor version. All memory values (configuration of probe as type, measuring unit etc. , calibration curve, measuring range, cleaning interval, calibration factor) however, are created twice. Therefore, the adequate sensor must first be chosen before each entry.

**In the middle of the LED-line, it is indicated which data set (of the first or the 2<sup>nd</sup> sensor) is currently selected.**



### 12.2 Probe types (special version „2 sensors“)

To enable the device to be operated with one probe only, the virtual type “no probe“ was additionally included. When this is selected no indication appears on the corresponding probe channel, neither the limit value nor the current output will be affected nor an error message will be put out.

### 12.3 Alarm values (special version „2 sensors“)

Exactly one alarm value with corresponding relay output (Alarm A or Alarm B) is assigned to each probe.

### 12.4 Error messages, error output (special version „2 sensors“)

The output “error“ is set as soon as one error message from at least one probe comes up within a certain time-span. The causes of error can be viewed in detail for each probe in the respective sub-menu “READ ERROR“.

The output “error“ is set back when none of the connected probes outputs an error message.

## **12.5 Calibration factor (special version „2 sensors“)**

Each probe has an own calibration factor. It can either be put in via the menu “CONFIGURATION“ , or it can be called up or changed during the running measurement by pressing the key “K“ (press once: sensor 1, twice: sensor 2). In the middle of the LED line it is indicated which correction factor of the 1<sup>st</sup> or 2<sup>nd</sup> probe is being selected.

## **12.6 Cleaning of the probe (special version „2 sensors“)**

Cleaning interval and –duration can be parametered separately for each probe. The hold-output is activated as long as the cleaning is active in at least one of the probes.

During the cleaning the measuring signal is frozen at the corresponding probe.

## **12.7 Current outputs (special version „2 sensors“)**

Current output „I-1“ is assigned to the 1<sup>st</sup> probe, current output „I-2“ to the 2<sup>nd</sup>.

## **12.8 Measured value output via serial interface (special version „2 sensors“)**

The measured values are put out by each probe in second-intervals as ASCII-string at the RS-232 interface (9600, N, 8, 1) (as long as the probe type “no probe“ has not been configured) .

Each measured value is marked from which probe (“1:“ or “2:“) it comes from.

## **12.9 Measured value indication via LED special version „2 sensors“)**

In automatic measuring operation, the measured value of the probe is indicated of which the main menu (that means 1<sup>st</sup> or 2<sup>nd</sup> PROBE – PARAMETER ENTRY, CALIBRATING,...) was called up last.

---

## 13. Technical Data

### 13.1 General information




Measuring principle:	Multi-beam pulsed-light, infra-red light with 880 nm wave length
Measuring range:	dependent on the measuring probe connected
Power supply:	115 - 230 V /, 50 / 60 Hz 24 V / AC-DC (optional)
Power consumption:	max. 25 VA
Measuring accuracy:	$\leq \pm 1\%$
Repeatability:	0.5 %
Analog output:	standard signal 0 - 20 mA or 4 - 20 mA galvanically separated
Permissible load:	max. 500 $\Omega$
Relay outputs:	2 alarm contacts free chosable 1 relay contact for probe cleaning 1 relay contact for error report 1 relay contact for hold
Switching capacity:	DC 30 V / 1 A AC 230 V / 2 A
Serial interface:	RS 232 (optional)
11	

### 13.2 Electronics unit


Ambient temperature:	-20...+60°C
Programming:	Menu-driven, microprocessor controlled
Displays:	LED display (14 mm) for actual measured value, 2-line LC display (5 mm) for programming measured value in FTU, NTU, g/l, mg/l, % and ppm
Keypad:	Dust- and water-proof foil keypad with 6 keys for menu control
Signal transmission:	max. 200 m from the sensor to the transformer
Connections:	Connector IP 67 between probe and transformer, ouputs on terminals
Version:	Field enclosure IP 65 / NEMA 4X
Weight:	3.5 kg

### 13.3 Dimensions

#### 13.3.1 Field enclosure



Back view:



## Annex

### Contents:

Connection of solenoid valves for cleaning

Measuring procedure - applications

CUM 740 - factory adjustments ( standard parameters)

Troubleshooting guide


    Error messages

    Error diagnosis

CUM 740 factory settings

Accessories

**Drive system for solenoid valves for cleaning**



## Measuring procedure - Applications

Measuring procedure	Physical Unit	Ranges	Type of probe	Typical application
Scattering light	mg/l ppm FTU NTU	2 ... 1000 FTU, NTU 2 ... 1000 mg/l (depends on media)	SSN	Treatment plant outlet, River water Process water, filtrate
Absorption light	g/l % mg/l ppm	0 ... 40 g/l NS* 0 ... 20 g/l PS*	SAH	Primary sludge Return activated sludge
		0 ... 12 g/l NS* 0 ... 6 g/l PS*	SAM	Centrifugate, Screened water, Sludge level, Activated sludge,
		0 ... 50 g/l NS* 0 ... 30 g/l PS*	SAV	Primary sludge, Digested sludge, Thickened sludge
Back scattering light	g/l %	10 ... 150 g/l NS*	SRH / SRM	Inlet centrifuge / press Thickened sludge Primary sludge, digested sludge

\* NS = Normal activated sludge

\* PS = Primary- or mixed sludge

## MTF- Factory settings (standard parameters) see 5.6 „configuration“

**Please note:** By entering the factory setting, all previous stored values will be overwritten.  
The correction factor is set to 0%.

Type of probe	CUS61/65-A	CUS65-C	CUS63/65-D	CUS64/65-E	CUS65-B	Free param.
Measuring unit	g/l	%	FTU	%	g/l	%
Analog output	4...20 mA					
Contacts	oper. current					
<b>No. calibr. points</b>	6	8	8	5	5	4
<b>Frequency 1 [Hz]</b>	4100	6500	6600	4050	3400	8000
<b>Frequency 2 [Hz]</b>	3520	6000	5920	3700	3250	6000
<b>Frequency 3 [Hz]</b>	3250	5750	5320	3200	3200	4000
<b>Frequency 4 [Hz]</b>	2950	5470	4920	2800	2900	2000
<b>Frequency 5 [Hz]</b>	2650	5150	4620	2200	2200	-
<b>Frequency 6 [Hz]</b>	2370	4900	4320	-	-	-
<b>Frequency 7 [Hz]</b>	-	4650	4020	-	-	-
<b>Frequency 8 [Hz]</b>	-	4400	3600	-	-	-
<b>Concentration 1</b>	0.0	0.0	0.5	1.0	0.0	1.0
Concentration 2	2.0	1.0	5	2.0	3.0	3.0
Concentration 3	3.0	2.0	20	4.0	5.0	10.0
Concentration 4	4.0	3.0	50	6.0	10.0	30.0
Concentration 5	5.0	4.0	100	8.0	20.0	-
Concentration 6	6.0	5.0	200	-	-	-
Concentration 7	-	6.0	400	-	-	-
Concentration 8	-	7.0	1000	-	-	-
<b>Range start</b>	0.0	0.0	0.0	1.0	0.0	1.0
<b>Range end</b>	10.0	10.0	1000	10.0	20.0	30.0
<b>Alarm A</b>	10.0	10.0	200	10.0	10.0	10.0
<b>Alarm B</b>	10.0	10.0	400	10.0	20.0	10.0
<b>Damping [s]</b>	20	20	20	20	20	20
<b>Clean. interv. [min]</b>	0	0	0	0	0	0
<b>Clean. dur. [s]</b>	1	1	1	1	1	1
normal operating ranges are within the frequency stroke of:	4000 Hz -	6500 Hz -	6600 Hz -	4100 Hz -	3500 Hz -	-
	1000 Hz	4000 Hz	3600 Hz	1000 Hz	1000 Hz	

## Troubleshooting guide

**Attention:** Before exchanging the fuses disconnect the device from the mains!  
Start the device only with inserted and screwed probe plug!  
Plug in or out the probe plug only when the device is off!

### Causes of error :

Causes for errors in the system may be found at the measuring probe, the measuring transformer, the cable section between both units and in the field of mains supply.

### First steps:

1. Localize errors, if probe or measuring electronic defective, by exchange of components (if available)
2. Test probe frequency by twice pressing the ENTER key in the “measurement-mode” (frequency indication on LC-display) – see error messages (0 Hz, or 505 Hz), 5.8
3. Test power supply and fuse (F1).

For further support in troubleshooting please refer to your sales organisation responsible (see back page of these Operating Instructions for addresses).

## Error messages

<b>The signal output “error” is only set when a cause of error exists for at least 10 seconds without interruption.</b>
<b>Over-concentration</b> is displayed when the predetermined range end is exceeded more than twice
<b>Wrong type of probe</b> is shown when the connected probe does not correspond to the selected type.
<b>No probe signal</b> is shown when the measuring transformer does not receive a frequency signal from the probe (e.g. cable breakthrough) This error results in a frequency display of 0 Hz independently from the output “error”.
<b>No probe signal / probe soiled</b> is shown when the measuring transformer does not receive a frequency signal from the probe and in addition receives a status message (e.g. soiled probe windows / does not apply for the thick sludge probes CUS 64 / 65-E). Independent from the output “error” the error results in a frequency display of 505 Hz.
<b>Test calibration</b> is displayed when the calibration frequencies are closer than 15 Hz from each other (e.g. when the saved calibration frequencies were overwritten by mistake).

## Error diagnosis

Problem / error		Symptom	Possible cause	Measure
1	no function	no display, mains switch is not on	mains supply ⇒ mains fuse ⇒  mains switch defective ⇒	test feed test fuse in connection case return to manufacturer or order spare part
2	device loses programming after it has been stopped	random values in the memories	buffer-battery of the CPU is empty (lasts about 5 years), possibly EMV error.	return to manufacturer or order spare part
3	creeping display up to the real measured value	actualization of the display too sluggish	damping time too long	change damping time accordingly under “parameter entry”
4	no concentration measurement	no display of any measured value, frequency display “505 Hz” or “0Hz”	probe electronics defective ⇒ measuring window soiled ⇒	return to manufacturer  clean measuring window
5	no continuous output current	current output varying at stable probe frequency	current output defective possible EMV error	return to manufacturer
6	output signals are not set	correspondent output relay does not actuate despite LED-display	relay contact pasted, because efficiency of the relay exceeded; relay defective	Return to manufacturer

## CUM 740 - parameters

**Serial-Number:** \_\_\_\_\_

**Sensor - 1, No.:** \_\_\_\_\_ Sensor - 2, see next page

**Software-Version:** PO - \_\_\_\_\_

### 1. Configuration

Type of probe	Factory settings <input type="checkbox"/> yes <input type="checkbox"/> no	Measurement unit	Calibration factor
---------------	--	------------------	--------------------

Analog output	Alarm A	Alarm B	Error contact
---------------	---------	---------	---------------

**2. Frequency [Hz]** →

**3. Solids input** →

[            ]  
Unit

	1. _____	2. _____
3. _____	4. _____	5. _____
6. _____	7. _____	8. _____

### 4. Parameter entry

Range start	Range end	Alarm A	Alarm B
-------------	-----------	---------	---------

Damping	Cleaning interval	Cleaning duration
---------	-------------------	-------------------

**5. Remarks:** \_\_\_\_\_

## CUM 740 - parameters

**Serial-Number:** \_\_\_\_\_

**Sensor - 2, No.:** \_\_\_\_\_ Sensor - 1, see previous page

**Software-Version:** PO - \_\_\_\_\_

### 1. Configuration

Type of probe	Factory settings <input type="checkbox"/> yes <input type="checkbox"/> no	Measurement unit	Calibration factor
---------------	--	------------------	--------------------

Analog output	Alarm A	Alarm B	Error contact
---------------	---------	---------	---------------

<b>2. Frequency [Hz]</b> →  <b>3. Solids input</b> → [            ] Unit		1. _____	2. _____	
		3. _____	4. _____	5. _____
		6. _____	7. _____	8. _____

### 4. Parameter entry

Range start	Range end	Alarm A	Alarm B
-------------	-----------	---------	---------

Damping	Cleaning interval	Cleaning duration
---------	-------------------	-------------------

**6. Remarks:** \_\_\_\_\_

---

## Accessories

### Sensors

**TurbiMax W CUS 61**

Turbidity and solids content sensor for medium concentrations  
Technical Information TI 228C/07/en, Order No.: 51504289

**TurbiMax W CUS 62**

Turbidity and solids content sensor for high concentrations  
Technical Information TI 229C/07/en, Order No.: 51504291

**TurbiMax W CUS 63**

Turbidity and solids content sensor for low concentrations  
Technical Information TI 230C/07/en, Order No.: 51504293

**TurbiMax W CUS 64**

Turbidity and solids content sensor for highest concentrations  
Technical Information TI 231C/07/en, Order No.: 51504295

**TurbiMax W CUS 65**

Turbidity and solids content sensor for low to highest concentrations  
Technical Information TI 370C/07/en, Order No.: 51512873

### Attachment

**Immersion pipe**

Immersion pipe for sensor immersion in basins. Material: stainless steel 1.4404 (AISI 316L) (pipe), stainless steel 1.4571 (AISI 316Ti) (fitting).

**Wall attachment for immersion pipe**

Wall attachment for immersion pipe attachment to basins or channels.

Material: stainless steel 1.4301 (AISI 304)

Order No.: 51503581

**Counter plate**

Counter plate to fix the immersion pipe attachment. Material: stainless steel 1.4301 (AISI 304).

Order No.: 51512992

### Assemblies

**Installation assembly**

CleanFit CUA 451

Retractable assembly with ball valve for pipe installation

Material: stainless steel 1.4404 (AISI 316L)

Technical Information TI 369C/07/en, Order No. 51512836

---

## Connection accessories

### Extension cable

Extension cable, length 10 m, shielded, with SXP plug and SXK coupling. Ingress protection IP 67.

Order No.: 51503633

### Plugs

SXP plug, 7-pole

Order No.: 51504027

SXK coupling, 7-pole

Order No.: 51504025

### Junction box

Junction box for extension of cable connection between sensor and instrument. Sensor cable input SXB socket, cable output Pg 11 cable gland. Material: Makrolon®. Ingress protection IP 67.

Order No.: 51503632

## Europe

### Austria

□ Endress+Hauser Ges.m.b.H.  
Wien  
Tel. ++43 (1) 880 56-0, Fax (1) 880 56-35

### Belarus

Belorgsintez  
Minsk  
Tel. ++375 (172) 2631 66, Fax (172) 2631 11

### Belgium / Luxembourg

□ Endress+Hauser S.A./N.V.  
Brussels  
Tel. ++32 (2) 2 48 06 00, Fax (2) 2 48 05 53

### Bulgaria

INTERTECH-AUTOMATION  
Sofia  
Tel. ++359 (2) 66 48 69, Fax (2) 9 63 13 89

### Croatia

□ Endress+Hauser GmbH+Co.  
Zagreb  
Tel. ++385 (1) 6 63 77 85, Fax (1) 6 63 78 23

### Cyprus

I+G Electrical Services Co. Ltd.  
Nicosia  
Tel. ++357 (2) 48 47 88, Fax (2) 48 46 90

### Czech Republic

□ Endress+Hauser GmbH+Co.  
Praha  
Tel. ++42 00 (26) 6 78 42 00, Fax (26) 6 78 41 79

### Denmark

□ Endress+Hauser A/S  
Soborg  
Tel. ++45 (70) 13 11 32, Fax (70) 13 21 33

### Estonia

Elvi-Aqua  
Tartu  
Tel. ++372 (7) 4 22 72 6, Fax (7) 4 22 72 7

### Finland

□ Endress+Hauser Oy  
Espoo  
Tel. ++358 (9) 8 59 61 55, Fax (9) 8 59 60 55

### France

□ Endress+Hauser  
Huningue  
Tel. ++33 (3) 89 69 67 68, Fax (3) 89 69 48 02

### Germany

□ Endress+Hauser Meßtechnik GmbH+Co.  
Weil am Rhein  
Tel. ++49 (76 21) 9 75 01, Fax (76 21) 9 75 55 55

### Great Britain

□ Endress+Hauser Ltd.  
Manchester  
Tel. ++44 (1 61) 2 86 50 00,  
Fax (1 61) 9 98 18 41

### Greece

I & G Building Services Automation S.A.  
Athens  
Tel. ++30 (1) 9 24 15 00, Fax (1) 9 22 17 14

### Hungary

Mile Ipari-Elektro  
Budapest  
Tel. ++36 (1) 2 61 55 35, Fax (1) 2 61 55 35

### Iceland

Vatnshreinsun HF  
Reykjavik  
Tel. ++354 (5) 61 96 16, Fax (5) 61 96 17

### Ireland

Flomeaco Company Ltd.  
Kildare  
Tel. ++353 (45) 86 86 15, Fax (45) 86 81 82

### Italy

□ Endress+Hauser Italia S.p.A.  
Cernusco s/N Milano  
Tel. ++39 (02) 92 10 64 21,  
Fax (02) 92 10 71 53

### Latvia

Raita Ltd.  
Riga  
Tel. ++371 (7) 31 28 97, Fax (7) 31 28 94

### Lithuania

Agava Ltd.  
Kaunas  
Tel. ++370 (7) 20 24 10, Fax (7) 20 74 14

### Netherlands

□ Endress+Hauser B.V.  
Naarden  
Tel. ++31 (35) 6 95 86 11, Fax (35) 6 95 88 25

### Norway

□ Endress+Hauser A/S  
Tranby  
Tel. ++47 (32) 85 98 50, Fax (32) 85 98 51

### Poland

□ Endress+Hauser Polska Sp. z o.o.  
Warszawy  
Tel. ++48 (22) 7 20 10 90, Fax (22) 7 20 10 85

### Portugal

Tecnisis - Tecnica de Sistemas Industriais  
Linda-a-Velha  
Tel. ++351 (1) 4 17 26 37, Fax (1) 4 18 52 78

### Romania

Romconseng SRL  
Bucharest  
Tel. ++40 (1) 4 10 16 34, Fax (1) 4 10 16 34

### Russia

□ Endress+Hauser Moscow Office  
Moscow  
Tel. ++7 09 (5) 1 58 75 71, Fax (5) 1 58 98 64

### Slovak Republic

Transcom Technik s.r.o.  
Bratislava  
Tel. ++421 (74) 4 88 86 84, Fax (74) 4 88 71 12

### Slovenia

□ Endress+Hauser D.O.O.  
Ljubljana  
Tel. ++386 (61) 1 59 22 17, Fax (61) 1 59 22 98

### Spain

□ Endress+Hauser S.A.  
Barcelona  
Tel. ++34 (93) 4 80 33 66, Fax (93) 4 73 38 39

### Sweden

□ Endress+Hauser AB  
Sollentuna  
Tel. ++46 (8) 5 55 1 16 00, Fax (8) 5 55 1 16 00

### Switzerland

□ Endress+Hauser AG  
Reinach/BL 1  
Tel. ++41 (61) 7 15 75 75, Fax (61) 7 11 16 50

### Turkey

Intek Endüstriyel Ölçü ve Kontrol Sistemleri  
Istanbul  
Tel. ++90 (2 12) 2 75 13 55,  
Fax (2 12) 2 66 27 75

### Ukraine

Industria Ukraïna  
Kiev  
Tel. ++380 (44) 2 68 81, Fax (44) 2 69 08

### Yugoslavia

Meris d.o.o.  
Beograd  
Tel. ++381 (11) 4 44 61 64, Fax (11) 4 44 19 66

## Africa

### Egypt

Anasia  
Heliopolis/Cairo  
Tel. ++20 (2) 4 1 79 00, Fax (2) 4 1 79 00

### Morocco

Oussama S.A.  
Casablanca  
Tel. ++2 12 (2) 24 13 38, Fax (2) 40 26 57

### Nigeria

J F Technical Invest. Nig. Ltd.  
Lagos  
Tel. ++234 (1) 6 22 23 45 46, Fax (1) 6 22 23 45 48

### South Africa

□ Endress+Hauser Pty. Ltd.  
Sandton  
Tel. ++27 (11) 4 44 13 86, Fax (11) 4 44 19 77

### Tunisia

Controle, Maintenance et Regulation  
Tunis  
Tel. ++2 16 (1) 7 90 37 7, Fax (1) 7 88 59 5

## America

### Argentina

□ Endress+Hauser Argentina S.A.  
Buenos Aires  
Tel. ++54 (1) 1 45 22 79 70,  
Fax (1) 1 45 22 79 09

### Bolivia

Tritec S.R.L.  
Cochabamba  
Tel. ++5 91 (42) 5 69 93, Fax (42) 5 09 81

### Brazil

□ Samson Endress+Hauser Ltda.  
Sao Paulo  
Tel. ++55 (11) 5 03 31 34 55,  
Fax (11) 5 03 31 30 67

### Canada

□ Endress+Hauser Ltd.  
Burlington, Ontario  
Tel. ++1 (905) 6 81 92 92,  
Fax (905) 6 81 94 44

### Chile

DIN Instrumentos Ltda.  
Santiago  
Tel. ++56 (2) 2 05 01 00, Fax (2) 2 25 81 39

### Colombia

Colsein Ltd.  
Bogota D.C.  
Tel. ++57 (1) 2 36 76 59, Fax (1) 6 10 78 68

### Costa Rica

EURO-TEC S.A.  
San Jose  
Tel. ++5 06 (2) 96 15 42, Fax (2) 96 15 42

### Ecuador

Insetec Cia. Ltda.  
Quito  
Tel. ++5 93 (2) 2 69 1 48, Fax (02) 46 18 33

### Guatemala

ACISA Automatizacion Y Control Industrial S.A.  
Ciudad de Guatemala, C.A.  
Tel. ++5 02 (3) 34 59 85, Fax (2) 32 74 31

### Mexico

□ Endress+Hauser I.I.  
Mexico City  
Tel. ++52 (5) 5 68 89 65, Fax (5) 5 68 84 18

### Paraguay

Incoel S.R.L.  
Asuncion  
Tel. ++5 95 (21) 21 39 89, Fax (21) 22 65 83

### Uruguay

Circular S.A.  
Montevideo  
Tel. ++5 98 (2) 9 25 75 85, Fax (2) 9 29 51 51

### USA

□ Endress+Hauser Inc.  
Greenwood, Indiana  
Tel. ++1 (3 17) 5 35 71 38,  
Fax (3 17) 5 35 84 89

### Venezuela

H. Z. Instrumentos C.A.  
Caracas  
Tel. ++58 (2) 9 44 09 66, Fax (2) 9 44 45 54

## Asia

### China

□ Endress+Hauser Shanghai  
Instrumentation Co. Ltd.  
Shanghai  
Tel. ++86 (21) 54 90 23 00,  
Fax (21) 54 90 23 03

### □ Endress+Hauser Beijing Office

Beijing  
Tel. ++86 (10) 68 34 40 58,  
Fax (10) 68 34 40 68

### □ Endress+Hauser (H.K.) Ltd.

Hong Kong  
Tel. ++8 52 (2) 5 28 31 20, Fax (2) 8 65 41 71

### India

□ Endress+Hauser India Branch Office  
Mumbai  
Tel. ++91 (22) 8 52 14 58, Fax (22) 8 52 19 27

### Indonesia

PT Grama Bazita  
Jakarta  
Tel. ++62 (21) 7 97 50 83, Fax (21) 7 97 50 89

### Japan

□ Sakura Endress Co., Ltd.  
Tokyo  
Tel. ++81 (4 22) 54 06 11, Fax (4 22) 55 02 75

### Malaysia

□ Endress+Hauser (M) Sdn. Bhd.  
Petaling Jaya, Selangor Darul Ehsan  
Tel. ++60 (3) 7 33 48 48, Fax (3) 7 33 88 00

### Pakistan

Speedy Automation  
Karachi  
Tel. ++92 (21) 7 72 29 53, Fax (21) 7 73 68 84

### Papua New Guinea

SBS Electrical Pty Limited  
Port Moresby  
Tel. ++675 (3) 25 11 88, Fax (3) 25 95 56

### Philippines

Brenton Industries Inc.  
Makati Metro Manila  
Tel. ++63 (2) 6 38 80 41, Fax (2) 6 38 80 42

### Singapore

□ Endress+Hauser (S.E.A.) Pte., Ltd.  
Singapore  
Tel. ++65 (5) 66 82 22, Fax (2) 66 68 48

### South Korea

□ Endress+Hauser (Korea) Co., Ltd.  
Seoul  
Tel. ++82 (2) 6 58 72 00, Fax (2) 6 59 28 38

### Taiwan

Kingjarl Corporation  
Taipei R.O.C.  
Tel. ++886 (2) 27 18 39 38, Fax (2) 27 13 41 90

### Thailand

□ Endress+Hauser Ltd.  
Bangkok  
Tel. 66 (2) 9 96 78 11 20, Fax (2) 9 96 78 10

### Vietnam

Tan Viet Bao Co. Ltd.  
Ho Chi Minh City  
Tel. ++84 (8) 8 33 52 25, Fax (8) 8 33 52 27

### Iran

Telephone Technical Services Co. Ltd.  
Tehran  
Tel. ++98 (21) 8 74 67 50, Fax (21) 8 73 72 95

### Israel

Instrumetrics Industrial Control Ltd.  
Tel-Aviv  
Tel. ++972 (3) 6 48 02 05, Fax (3) 6 47 19 92

### Jordan

A.P. Parpas Engineering S.A.  
Amman  
Tel. ++962 (6) 4 64 32 46, Fax (6) 4 64 57 07

### Kingdom of Saudi Arabia

Anasia  
Jeddah  
Tel. ++966 (2) 6 71 00 14, Fax (2) 6 72 59 29

### Kuwait

Kuwait Maritime & Mercantile Co. K.S.C.  
Safat  
Tel. ++965 (2) 44 14 81, Fax (2) 44 14 86

### Lebanon

Nabil Ibrahim  
Jbeil  
Tel. ++961 (3) 25 40 52, Fax (9) 54 80 38

### Sultanate of Oman

Mustafa & Jawad Science & Industry Co.  
L.L.C.  
Ruwi  
Tel. ++968 (60) 20 09, Fax (60) 70 66

### United Arab Emirates

Descon Trading EST.  
Dubai  
Tel. ++971 (4) 65 36 51, Fax (4) 65 32 64

### Yemen

Yemen Company for Ghee and Soap Industry  
Taiz  
Tel. ++976 (4) 23 06 64, Fax (4) 21 23 38

## Australia + New Zealand

### Australia

ALSTOM Australia Ltd.  
Sydney  
Tel. ++61 (2) 97 22 47 77, Fax (2) 97 22 48 88

### New Zealand

EMC Industrial Instrumentation  
Auckland  
Tel. ++64 (9) 4 15 51 10, Fax (9) 4 15 51 15

## All other countries

□ Endress+Hauser GmbH+Co.  
Instruments International  
D-Weil am Rhein  
Germany  
Tel. ++49 (76 21) 9 75 02, Fax (7 621) 9 75 34 5

□ Members of the Endress+Hauser group



51504299

Endress+Hauser

The Power of Know How

