

















## Manufacturer Information

for users regarding software updates (following the NAMUR recommendation 53)

### 1 Type of device

□ Field device / signal processing device

☐ Monitoring- / operation system / hand held terminal etc.

☐ Modem / interface

Manufacturer : Endress+Hauser

Device : Liquistation

Type : CSF48, CSF34

Previous software : 1.05.00

version

How can the previous software version number be identified:

(a) With standard Fieldbus communication

(b) with FieldCare/DTM

(c) Display

#### 2 Software

New software version : 1.05.01

Description of the modification in comparison with the predecessor version:

#### Samper - New Features, Enhancements & Improvements:

- Progress indication at binary output for manual sampling
- Fixed flow totalizer to enable flow dependent sampling programs

#### **Enhancements & Improvements:**


- Support of the optical sensors for fresh water turbidity CUS52D
- improved software stability for the Liquiline device platform
- Corrected diagnostic message F262 "Electronics module no communication"
- For easy commissioning via the Ethernet network the factory setting is DHCP = on

#### Known issue with this software version

- Update from 1.04.xx to 1.05.00 or 1.05.01 will lose all Profibus settings.
   Work around: reset device and set all settings manually new! Copying a stored configuration file will lead to the same issue.
- In some cases the export of the logbooks via the webserver was not complete. In this case please repeat the download or transfer the data with the sd card.

#### 3 Compatibility

Is the operating tool compatible with the installed device software?























# Manufacturer Information

for users regarding software updates (following the NAMUR recommendation 53)

| <ul><li>✓ Yes</li><li>☐ No, description:</li></ul>  |          |                       |  |
|---|----------|-----------------------|--|
| Is a software update generally recommended?   |          |                       |  |
| ☐ Yes, reason:  |          |                       |  |
| The software update can be performed by means of  • SD card   |          |                       |  |
| No, reason:     ■ No. |          |                       |  |
| Update not recommended  |          |                       |  |
| Instruction manual  |          |                       |  |
| Is a new instruction manual necessary due to the modification of the software?  |          |                       |  |
| ☐ Yes<br>☑ No   | on maria | arriccessury due to t | are mounication of the software.       |
| Which manual corresponds to the new software:   |          |                       |  |
| Device  | Commun   | ication options       | Manual Marking                         |
| CSF48, CSF34  | All      | BA00443CDE.pdf        | Liquistation Commissioning             |
|   |          | BA00463CDE.pdf        | Liquistation Maintenance & Diagnostics |
|   |          | BA00464CDE.pdf        | Liquistation Operation & Setting       |
|   |          | BA00467CDE.pdf        | Liquistation Calibration               |
| The new instruction manuals can be referred in Internet: <a href="http://www.endress.com">http://www.endress.com</a> - area "DOWNLOAD" - declaration of the device and kind of manual   |          |                       |  |
| Price   |          |                       |  |
| Change in price of device in comparison with the predecessor version?   |          |                       |  |
| <ul><li>☐ Yes, new list price and update costs (without installation) are enclosed</li><li>☑ No</li></ul>   |          |                       |  |



5

4