








Special Documentation

Mounting hints for weld-in adapter


Level and pressure measurement

TI00426F


QR-Code





1.




2.




3.




4.




5.





6.




7.








A0036469




G 1" Liquiphant M




RD52




G 3/4" d55
G 1" d53
G 1" d60
G 3/4" d50
G 3/4" d29



G 3/4" d55
G 1" d53
G 1" d60



G 3/4" d50
G 3/4" d29



5.

