

Manufacturer Information

for users regarding software updates
(following the NAMUR recommendation 53)

1 Type of Product

- Field device/signal processing device
- Software/hardware for device configuration/field communicator handheld/device drivers etc. Modem/interface
-

Manufacturer : Endress+Hauser Process Solutions AG
Product : **W@M Enterprise**
Type : **SWAM10B**

2 Software

Previous software version : 04.05.00

New software version : **04.06.00**

How can the previous software version number be identified? : Label on the DVD. The version number is also available directly in the headline of the application window and under the category “system information” on the home page.

Manufacturer Information

for users regarding software updates
(following the NAMUR recommendation 53)

Description of the
modification in comparison
with the predecessor version

: See W@M Enterprise release notes available on the DVD installation.

Scope of release:
9 bug fixes, 10 enhancements

Main enhancements:

- Device-in-device child devices can now be scrapped.
- Order code description for 3rd party devices supports now tabulation.
- Service / Repair events are now displayed.
- Excel export / import displays now the number of maximum characters as well as a description for type specific labels.
- Production and shipment events can now be created manually.

Main defects:

- Corrected TAG synchronization between Installed Base Assistant and Task Scheduler.
- Fixed few bugs for the W@M Enterprise synchronization such as TAG names synchronization and unwanted stops.
- Fixed device-in-device child device displays, from search and device list.
- Improved documents download waiting times.
- Improved performance for data export and devices moves.

Where to get the new
Software?

On demand to PC Process Solutions AG on following email address:
service@solutions.endress.com

Manufacturer Information

for users regarding software updates
(following the NAMUR recommendation 53)

3 Compatibility

Is the new product software compatible with the previous version, installed device driver components and operating tools?

- Yes
 No

Is a software update generally recommended?

- Yes
In general the software update is not mandatory but recommended. The W@M Enterprise 04.06.00 contains bug fixing as synchronization mistakes and Task Scheduler with Installed Base Assistant synchronization.
- No
Known issues are fixed.
Please refer to the Technical information (TI).

4 Instruction manual

Is a new instruction manual necessary due to the software modification?

- Yes
 No

The manual that corresponds to the actual software version is:

Product	Communication	Manual type	Document identifier
W@M		Operating Instructions	BA01272S/04/EN/05.19
Enterprise		Installation Guide	BA01273S/04/A3/02.15
SWAM10B		Technical Information	TI01240S/04/EN/01.15

Remarks:

The instruction manuals can be downloaded from the Internet:
Not available on internet but on software under „help“.

Manufacturer Information

for users regarding software updates
(following the NAMUR recommendation 53)

5 Price

Change in price in comparison with the predecessor version?

New list price and update costs (without installation).

- Yes
- No