

Manufacturer Information

for users regarding software and hardware updates
(following the NAMUR recommendation 53)

Field Xpert SMT50 1.06.00

New software version is released

1 Type of Product

- Software/hardware for device configuration/tablet/handheld/device drivers etc.
 Modem/interface

Manufacturer : Endress+Hauser Process Solutions AG
Product : **Field Xpert SMT50**
Type and order code : **SMT50**

2 Software

Previous software version : 1.00.00, 1.00.02, 1.01.00, 1.02.00, 1.03.00, 1.03.01, 1.04.00, 1.05.02, 1.05.03, 1.05.04, 1.05.05, 1,05.06

New software version : **1.06.00**

How can the previous software version number be identified? : Inside the current software version under menu item **? (Help) -> License -> Version**

Description of the modification in comparison with the predecessor version : Main changes to the software are:

- **New WiBu version with necessary bug fixes**
- **Braktooth vulnerability have been fixed**
- **Update from versions 1.05.03 and WiBu version 6.80 now possible**
- **DIBA improvements:**
 - **up to 200 assets can be created offline and**
 - **duplicate assets in combination with Edge are suppressed**
- **UX improvements and bug fixes**

Where to get the new Software?

If there is a valid maintenance period (Software Update Service) of the tablet and an Internet connection is detected, the Field Xpert SMT50 software automatically recognizes a new software version and downloads the software.

Manufacturer Information

for users regarding software and hardware updates
(following the NAMUR recommendation 53)

The user then can execute the installation or skip it.

If the maintenance period of the tablet has expired, we kindly ask you to contact the Endress+Hauser sales. (Topic: Field Xpert SMT50 Software-Update Contract, Software Update Service)

The communication DTMs and device DTMs, as well as the new drivers can be downloaded either automatically by having a valid SMT71 or from the Endress+Hauser software portal:

<https://software-products.endress.com/>

Additionally, we recommend to keep the Microsoft Windows operating system up-to-date.

3 Compatibility

Is the new product software compatible with the previous version?

Yes

No, reason:

Is a software update generally recommended?

Yes, reason:

It is recommended to update to the new software version of the Field Xpert SMT50. This ensures that Field Xpert can operate with newer field devices. Furthermore, the functionality have been extended and found issues have been solved.

No, reason:

Manufacturer Information

for users regarding software and hardware updates
(following the NAMUR recommendation 53)

4 Instruction manual

Is a new instruction manual necessary due to the software modification?

- Yes
 No

The manual that corresponds to the current version is:

Product	Document	Document identifier
Field Xpert SMT50	Operating Instructions (BA)	BA02053S/04/EN/03.22

The instruction manual can be downloaded from the Internet:

<https://www.endress.com/SMT50> -> Tab "Downloads / Operating Instruction"

5 Price

Is there a change in price in comparison with the predecessor version?

- Yes, new list price and update costs
 No